

PACE PAL® UNDERWATER PACE CLOCK INSTRUCTIONS



1. **POWER ON/OFF** (Press & Hold) 3 secs.
2. **BRIGHTNESS** (Press) - Three Levels
3. **START/STOP** (Press)
4. **MINUTES SET** (Press or Hold)
5. **SECONDS SET** (Press or Hold)
6. **CHARGING ACCESS PORT** (Threaded)

USE AS PACE CLOCK (COUNT-UP TIMER)

1. With display at 00:00, press "3" **START/STOP**.
2. Press "3" **START/STOP** again to pause and start.
3. To "RESET" press 4+5 simultaneously.
4. When continuously running, the clock counts up from 00:00 to 99:59, then turns off to conserve battery.

USE AS COUNT-DOWN TIMER

1. Press "4" **MIN** to set minutes.
2. Press "5" **SEC** to set seconds.
3. Press **START/STOP** to start or pause timing.
4. When the countdown is within 1 minute, the digits will turn red.

CHARGING TIPS

1. The [⚡] is always on when charging. It goes out when fully charged.
2. Lighted digits blink when battery is low and recharging is required.
3. The **CHARGING PORT PLUG "6"** IS THREADED. After charging press the **PLUG** fully in. Then it should easily screw in by hand. If it does not screw in smoothly and easily then it is "cross-threading." **Do not force it.** - Start over. - Re-seat the **PLUG "6"** **squarely into the threaded hole and hand screw it in securely, finger tight (Do not use tools.)**
4. **WARNING** - Please make sure the **CHARGING PORT PLUG** is securely in place prior to submersion or the case will **FLOOD** and the clock will be ruined.